VX2000 Pro V1.4.1 Release Notes

Release

1. 2026.09.02 VX2000 Pro V1.4.1

Supporting Software

1. Unico: V2.7.0
2. NovaLCT: V5.9.1 or later

New Features

1. None

Improvements

1. None

Changes

1. None

Bug Fixes

1. Fixed the occasional issue of abnormal display when sending the receiving card configuration file, calibration coefficients, or screen connection file via NovaLCT.
2. Fixed the issue where importing a file to Unico fails when the cabinet parameters saved in the file are the same, but the cabinet sizes are different.
3. Fixed the issue where saving calibration coefficients via NovaLCT fails.
4. Fixed the issue where 20 alarms are displayed on the Monitor interface in Unico after resetting to factory defaults.

Notes

1. None